

Troubleshooting 8 Blinks Failure (TC-P50ST50)

<https://www.weibemousepads.de/pdf/>

Blink Code	List of boards likely to cause this symptom.			
	No.1	No.2	No.3	No.4
8 Blinks	SS	A	SS2	Panel

Find information for TC-P50UT50 on the next slide)

